Board: ARC-45 (Dual CCD Video Board)
Revision: 3B
S/N: 385

Date	Action	Reason/Comment	Changer
25/09/13	Removed R147/R149	Remove Attenuation	David Atkinson
25/09/13	Remove 1K bias series resistors and replace with 100 Ohm: R126, R124, R127, R125, R133, R132, R144, R142, R145, R143	Reduce voltage drop across series resistor	David Atkinson